

## How to Connect Your Replacement XFT-2001 Foot Sensor via Bluetooth

To connect your new XFT-2001 Foot Sensor to your XFT-2001 unit, you need to reset the Bluetooth.

On the back of the calf unit, there is a small hole, as shown in the images below:

Use a paperclip to press in the reset button.

You will now be able to turn the two units on, and use them as normal.

